CENTRAL INTELLIGICE A LICI

Attachment

CHKALOV FOUNDRY FOR PRODUCTION OF

LOCOMOTIVE PARTS E

1. Foundry
2. Coal and Storage Area
3. Tempering Shop
4. Carpenter Shop
5. Administration Building
6. Gate Guardhouse

7. Main Entrance

9. Storage Tepot
10. Special Spur
11. Freight Yard with Storage
Sheds and Depots

